




EXISTING BUILDING

EXISTING ROCK WALLS


- Loading
- D10 SPEEDI-SHUTTLE 3,542 sqft
- D9 DOWBUILT 3,542 sqft
- D7 BLUEPRINT AUDIOTAPAL 1,500 sqft
- D6 JANITORIAL CLEANING SERVICES OF HAWAII 1,755 sqft
- D5 GREGORY RAY DOPP 1,755 sqft
- D4 KIRK HENRY 3,542 sqft
- D3 Available 1,500 sqft
- D1 BACKROADS UTILITY INC. 1,748 sqft
- Loading



- C9 KONA SPECIALTY INC. 1,755 sqft
- C8 KOA METALS INC. 1,764 sqft
- C7 COLLISION 3,542 sqft
- C6 DOWBUILT 1,755 sqft
- C5 WAHILA CONSTRUCTION 1,755 sqft

ROCK RETAINING WALL

- B9 TYRON TERAZONO & KALANEOA 1,755 sqft
- B8 KAILANI TOURS HAWAII LLC 1,755 sqft
- B7 RICHARD MICHELLE DAVID DAG 5,265 sqft
- B6,3,4 SCOTT CHELLING 7,087 sqft



- A8 EUROPEAN AUTO REPAIR 5,265 sqft
- A7 ALL NATURAL STONE FABRICATION, 5,265 sqft
- A6 KONA MUFFLER AND AUTO REPAIR 1,755 sqft
- A5 CANTOR BROS TRANSPORT 1,755 sqft
- Loading

5' WIDE SIDEWALK

RAMP

RAMP

ROAD "A"

ROAD "C"

